



# 2010 FALCON 900EX EASy, S/N 234

Manufacture date: May 15, 2009

U.S. Standard Airworthiness Certificate issued: March 17, 2010

Entry-into-Service date: August 31, 2010

Reg. #: N672WM

Total Time: 3598.1

Landings: 1650

#1 Engine (s/n P112897):	3585.5	CYCLES:	1643
#2 Engine (s/n P112898):	3598.1	CYCLES:	1650
#3 Engine (s/n P112899):	3598.1	CYCLES:	1650

Engine Type: Honeywell TFE731-60 (On MSP Gold)

APU (s/n P-592): Honeywell GTCP36-150(F) (On MSP Gold)

Maintenance: FlightDocs. HAPP expires July 2023 & CASP expires December 2023. **Inspections Due:** 12-month - January 2023; 1B at 4686 hours; 1C - January 2028 / 3C August 2028; Detailed Inspection of all Landing Gears – January 2028.

Exterior: Matterhorn White with custom accent stripes in Gloss Green & Gloss Yellow (Repainted August 2017 by DAS-LIT)

Interior: Beige leather seats, Tan patterned carpet, Birdseye Limba Hi-Gloss / Stained, Satin Champagne Gold plating.

Seating: 12 passengers: 4 forward club seats, 4-place mid-cabin dining group with opposing credenza, aft 3-place divan with opposing executive seat, aft lavatory, third crewmember seat

## EASy II – Cert. 4: Push-to-Load; WAAS-LPV; ADS-B Out; SVS; ADM; CPDLC – FANS 1/A & ATN B1

Flight Display System		Honeywell EASy (four 14-inch LCD's, two Cursor controls & two keyboards)
Flight Management System (FMS)	triple	Honeywell EASy
Global Positioning System (GPS)	dual	Honeywell
VHF Communication Systems	triple	Honeywell TR-866B
VOR/ILS/Marker Navigation System	dual	Honeywell NV-875B
DME Systems	dual	Honeywell DM-855
ADF Systems	dual	Honeywell DF-855
Mode S Transponder System	dual	Honeywell XS-858B
TCAS II System		ACSS TCAS 3000
Color Weather Radar System		Honeywell Primus 880
Communication Management Function		Honeywell EASy
Iridium Telecommunications		AirCell Axxess II with Data Interface Unit (DIU)
HF Communication Systems	dual	Collins HF-9000
Head-Up Guidance System		Rockwell Collins HGS-4860
Enhanced Ground Proximity Warning System		Honeywell EASy (EGPWS)
Micro Inertial Reference System	triple	Honeywell Laseref V
Radio Altimeter System	dual	Honeywell RT-300
Emergency Locator System (ELT)		ELTA ADT-406 (tri-frequency) with NAV interface
Cockpit Voice Recorder		Honeywell SSCVR (120 minutes)
Flight Data Recorder		Honeywell SSFDR (88 parameter)

**Additional Equipment:** Honeywell: three (3) AV-900 Flight Deck Audio, Selcal, LSS-860 Lightning Sensor System. **Honeywell EASy:** Central Maintenance Computer, Electronic Jeppesen Charts, Flight Deck Video Interface. **Securaplane Video Camera System (VCU-05):** Video Camera's – CAM-14 (Belly) & CMZ-03 (Glareshield). **Rockwell Collins:** 21-inch & 17-inch LCD monitor, one (1) dual DVD player, Airshow 4000 (non-interactive). Meggitt MK2 Secondary Flight Display, 115 cubic inch oxygen bottle

Asking Price: MAKE OFFER

Contact: Mark Verdesco ~ Director, Pre-owned Aircraft Sales

☎: (201) 541-4556 📠: (201)-541-4620 [www.dassaultfalcon.com](http://www.dassaultfalcon.com)

These specifications are presented as introductory information only. They do not constitute representations or warranties of any kind. Accordingly, you should rely on your own inspection of this aircraft. The aircraft is subject to prior sale, and/or removal from the market.