

**2001 FALCON 900EX S/N 096 (D-AHRN)**
**JAR-OPS1 Compliant**

2020 ELITE II Retrofit: ADS-B Out, WAAS LPV, CPDLC ATNB1, FANS-1A, 5ea. DU-875 LCD and 3ea. CDU-830

**AF TT** ..... **6704 TT**                                      **LANDINGS** ..... **3325 LDGS**  
**#1 ENGINE P112415**                                      6573                                      **CYCLES** ..... 3266  
**#2 ENGINE P112414**                                      6533                                      **CYCLES** ..... 3249  
**#3 ENGINE P112413**                                      6461                                      **CYCLES** ..... 3227

**ENGINE TYPE:** Honeywell TFE 731-60-1C **on MSP "GOLD"**


**APU (P-409):** AlliedSignal GTCP36-150(F) : 3645.54 hours (Installed in Dec. 2021) **on MSP "GOLD"**

**MAINTENANCE:** Under CAMP. Next "4C check" and L/G Overhaul due March 2026.

**EXTERIOR:** Complete Paint performed in 2014: White body without any stripes

**INTERIOR:** Cabin Refurb in 2014: Beige leather seats w/ white center insert, brown carpet w/ 100% wool /light silk waved lines, Cherry – Ash - Mahogany wood veneer, Nickel metal plating.

**SEATING:** 12 Pax floor plan w/ 3<sup>rd</sup> crew seat.  
Galley sliding pocket door,  
FWD and Aft Lavatories  
AFT cabin divider w/removable curtain,  
AFT cabin w/1 Sofa and executive Seat



<b>AP</b> .....		Honeywell Primus 2000
<b>FMS</b> .....	TRIPLE	Honeywell FMS 6.1.1 w/ CDU-830
<b>COMM (VHF)</b> .....	TRIPLE	Collins VHF-422C
<b>NAV (VHF)</b> .....	DUAL	Collins VIR-432
<b>ADF</b> .....	DUAL	Collins ADF-462
<b>DME</b> .....	DUAL	Collins DME-442
<b>ADC</b> .....	DUAL	Honeywell AZ840
<b>XPNDR</b> .....	DUAL	Collins TDR94D
<b>GPS</b> .....	DUAL	Honeywell SBAS (WAAS & EGNOS)
<b>SATCOM</b> .....		Honeywell MCS 7120 Level D/ Direct Cabin Router Wifi Activated (2.4 GHZ WAP, NO 3G) Falcon Connect
<b>HFCOM</b> .....	DUAL	HF-9000
<b>EFIS</b> .....	FIVE	DU-875 LCD
<b>RADAR</b> .....		Honeywell Primus 880
<b>RADIO ALTIMETER</b> .....		Honeywell AA-300
<b>EGPWS</b> .....		Honeywell MK V EGPWS with Windshear
<b>TCASS</b> .....		Collins TCAS II TTR-920 6 .04a 7.0/7 .1
<b>HEAD-UP GUIDANCE SYSTEM</b> .....		Flight Dynamics HGS-2860
<b>LRNAV</b> .....	TRIPLE	Honeywell Laseref IV
<b>CVR</b> .....		Honeywell 120 mn (980-4710-003)
<b>FDR</b> .....		Honeywell
<b>AIRSHOW</b> .....		AIRSHOW 410
<b>ELT</b> .....		Triband, 406 mHz

**ADDITIONAL EQUIPMENT:**

**Entertainment:** Collins Venue Audio/HD Entertaining System w/ Alto Subwoofers, Galley 16:9 TS, Blu-Ray Player, 2 ea. 18" HD Bulkhead LCD monitors, 4 ea. 9" HD Plug'in LCD monitors, 8 ea. Rosen receptacles, Ipod Electronic control module and Docking cradle.

**Galley-Aux Galley:** Central Water System, Microwave, High temp Oven.

**Misc:** Flightdeck Video Camera System, Securaplane 450 Aircraft Security System, B.F. Goodrich Stormscope Weather Mapping, EMTEQ LED direct/indirect lighting, Electronic portable checklist, 115 VAC / 60 Hz (1200VA), Teleflex recognition lights.

**SB Applied:** Brake/Wheel Well Heat, Increase MTOW.

**CONTACT:**

**Dominique Cruchon** - PRE-OWNED AIRCRAFT SALES DIRECTOR - ☎: + 33 1 47 11 60 71 - @: Dominique.Cruchon@dassault-aviation.com

**Yvon Desvignes** - PRE-OWNED AIRCRAFT SALES MANAGER - ☎: + 33 1 47 11 61 24 - @: Yvon.Desvignes@dassault-aviation.com

Aircraft pictures available by e-mail upon request. (www.falconjet.com)

SPECIFICATIONS SUBJECT TO VERIFICATION AIRCRAFT SUBJECT TO PRIOR SALE OR REMOVAL FROM THE MARKET